

WWS800/850

Bluetooth Class ID setting

Firmware version 5.58 introduces a change to the Bluetooth ClassID used by the scanner. When connecting by Bluetooth HID to some Android devices, this will cause the scanner to appear as a keyboard, and will not allow you to enter the pairing code for the scanner.

If your device is unable to pair with the default settings, scan Enter Setup, Android Compatible ClassID, Update, then retry the pairing operation.

If you need to return to the default, scan Enter Setup, Default ClassID, Update.



Enter Setup




Android Compatible
ClassID

OR



Default
ClassID



Update